

# Deepwater Horizon Disaster

Scientia Panel: “The BP Deepwater Horizon Catastrophe  
Causes, Consequences, and Cures”

**Satish Nagarajaiah**

**Professor of Civil and Mechanical Engineering**

Dept. of Civil & Env. Eng. And Dept. of Mechanical Eng. & Material Sc.

**Rice University, Houston, TX, USA**

Disclaimer: This study is meant to be purely technical documentation of events and causes. It is not meant to place blame on any individual or company or industry or government.

# Deepwater Horizon Rig



Source: MMS and BP

# April 20, 2010



- At approximately 10 pm Horizon Rig disaster started
- BLOWOUT: Initial explosion due to Gas/Oil/Mud surge and ignition upon entry into the engine room
- Fire starts and power failure
- Violent vibrations that shook the entire rig reported
- Second explosion
- Rig evacuated and fire/containment response and rescue begins by nearby vessels

# Horizon Rig April 20/21/22, 2010



Source: MMS/AP/flickr

# Horizon Before/After Collapse




Source: Live Science

# Well Schematic Mississippi Canyon 252 #1-01

from Halliburton

**Cement Seal Lacking**



Rig Floor = 75'

Water Depth 5,067'

Once the drilling mud in the riser is displaced with seawater, the annular seal(s) at the top of the casing begins to fail due to the large pressure differential between the wellbore annular space and the riser

36" @ 5,321'

28" @ 6,217'

22" @ 7,937'

18" @ 8,969'

16" @ 11,585'

13 5/8" @ 13,145'

Rigel Tex L Sand (Well Flowed / 13305') probably did not contribute to this incident

11 7/8" @ 15,103'

Oil & Gas moves up wellbore in the annular space outside of the 7" x 9 7/8" casing

9 7/8" @ 17,168'




Pay Zone

Zone of Lost Circulation

7" x 9 7/8" @ 18,360'

# Cementing Procedure



## How the cementing process works

1 A lower plug is placed through the pipe to force drilling mud down. Wet cement is then pumped in.

2 A solid upper plug pushes the remaining wet cement in the pipe down toward the lower plug, which opens up.

3 Cement travels through a one-way valve and fills the space between the pipe and drilled hole.







Figure Source: NYT

# Well Control - Barriers

- **Primary Barriers for Well Control**
  - **Static Equilibrium** - Downward Weight of the Drill Mud in the Drill Pipe is Equal to the Upward Oil/Gas or Formation Pressure
  - **Well Design** - Wellhead Seal and Multiple Casing Barriers
- **Secondary Barrier for Well Control**
  - **Blowout Preventer (BOP) Rams Activation**
  - **Last resort Blind Shear Ram Activation**



# Blow Out Preventer (BOP) 5 Story Tall



*The blowout preventer is 54 feet tall.*

**ANNULAR PREVENTERS**  
Can create a seal around the drill pipe or seal off an open wellbore when there is no pipe.

**CONTROL PODS**  
Receive electrical signals from the rig and direct the movement of hydraulic fluid. Upper portion has electrical parts; the lower portion has hydraulic valves. Only one pod is activated at a time.

**BLIND SHEAR RAM**  
Cuts the drill pipe and completely seals the well.

**CASING SHEAR RAM**  
Cuts drill pipe or casing in an emergency when the rig needs to disconnect from the well quickly.


**ACCUMULATORS**  
Store fluid sent from the rig. During an emergency, pressurized fluid from these canisters can provide force to power the blind shear ram.

**PIPE RAMS**  
Seal off the space between the outside of the drill pipe and the wellbore and keep the pipe centered.

**TEST RAM**  
Used to test the rams above it.


# Blow Out Preventer (BOP)


- A Series of Rams (Valves) Stacked one top of another
- Forms Secondary Barrier
- Last Resort Blind Shear Ram



Graphics Source: NYT

# Blow Out Preventer – Blind Shear Ram





Missing lockdown sleeve allows annular seal to fail

Missing lockdown sleeve allows annular seal to fail, gas/oil rushes to the rig floor

Methane Gas Bubble/oil rushes up the annular space from 18000 ft to 5000 ft


Casing/Cementing Fails

# Sequence of Events


- **Well System Failure**
  - Cement plug failure
  - Wellhead Seal Assembly Failure
- **Well Control Failure**
  - Mud Removed – Resulting in Upward Gas/Oil Pressure Greater than Downward Weight of the Drill Mud in the Drill Pipe – **PRIMARY BARRIER LOST**
- **Blowout Preventer Failure**
  - **SECONDARY BARRIER LOST**
- **Blowout with Methane Gas Bubble Rising to Rig Floor**
- **Ignition and Ensuing Explosion and Fire**

# Loss of Primary Well Control Procedures – Negative Test Setups


Negative Test Standard Procedure



Negative Test Approved on MMS Permit



Negative Test Setup at 4/20 17:45




# Loss of Primary Well Control

## Review of Procedures

- **Circulate out riser 20:00 to 21:08**
  - Mud circulation out prior to second plug – well reaches **highest underbalanced pressure** to this point
  - Shut down for static **sheen test** to begin going over board with water-based spacer
- **Areas of Investigation**
  - Flow changes and volumes
  - Mud transfers
  - Flow sensors accuracy
    - ✓ *Require Sperry Sun system set up details and calibration records*

**2000 psi reduction in back-pressure**  
**No mechanical bridge plug**  
**No upper cement plug**  
**No annular seal hold-down**

*Not all information has been verified or corroborated.  
Subject to review based on additional information or analysis.*



# Loss of Primary Well Control


## Review of Procedures (continued)

- **Flow Show at 20:58**

- Trip tank being discharged to pits through flow line (normal procedures ahead of change from oil to water mud in active system)
  - ✓ At same point pumps ramp down for stop at static sheen test
- Increased flow out due to discharge of trip tank
  - ✓ Driller expected to see flow increase
  - ✓ Flow returned near pre-tank discharge level when trip tank pump stopped, THEN increased
  - ✓ Potentially masked the gain

- **Area of Investigation**

- Complete review of all volumes and real time data (received 5/24)
- Use of trip tank in operation
- Sperry Sun sensors failure to record a flow out after 21:10





Source: BP OCS-G 32306 001 ST00BP01 Mississippi Canyon 252 Macondo, Last 2 hours before end of transmission

Source: Transocean



# Containment Response (Cap Assembly)




A perforated pipe was designed to allow oil and gas to escape during installation of the cap. It will be removed when the cap is closed.

**SEALING CAP**  
 The new cap has three rams, or valves, similar to ones on the well's blowout preventer. Once the cap is installed, the rams will be closed to stop the flow of oil to allow engineers to take pressure readings of the well.

Anti-freeze is being pumped here to avoid the formation of icelike hydrates that could affect the locking mechanism.


A 12-foot tall connector pipe was bolted onto the top of the blowout preventer.

# Static Kill



# Containment Response (Relief Wells)

Mid August




Source: BP

# Oil Spill Magnitude

## Major accidental oil spills

Million barrels



## Largest recent US oil spill

Exxon Valdez  
USA, 1989



Source: Oil Spill Intelligence Report